

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-5/7/2008	Southwest Area (sidewalk bridge level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST2-5/7/2008	Southeast Area (sidewalk bridge level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST4-5/7/2008	Northwest Area (street-level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST5-5/7/2008	Firehouse #10 (roof level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-5/7/2008	North Side Sidewalk Bridge	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-5/7/2008	Station 10 Field Duplicate	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-5/7/2008	90 Trinity Place (roof level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST13-5/7/2008	Marriott Hotel, 38th Floor (roof level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-5/7/2008	West Face - South end at corner (scaffolding level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST15-5/7/2008	South Face - East end at corner (scaffolding level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST16-5/7/2008	East Face - North end at corner (scaffolding level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST17-5/7/2008	North Face - West end at corner (scaffolding level)	5/7/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-5/8/2008	Southwest Area (sidewalk bridge level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST2-5/8/2008	Southeast Area (sidewalk bridge level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST4-5/8/2008	Northwest Area (street-level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST5-5/8/2008	Firehouse #10 (roof level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST10-5/8/2008	North Side Sidewalk Bridge	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST100-5/8/2008	Station 10 Field Duplicate	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST11-5/8/2008	90 Trinity Place (roof level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST13-5/8/2008	Marriott Hotel, 38th Floor (roof level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST14-5/8/2008	West Face - South end at corner (scaffolding level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST15-5/8/2008	South Face - East end at corner (scaffolding level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST16-5/8/2008	East Face - North end at corner (scaffolding level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST17-5/8/2008	North Face - West end at corner (scaffolding level)	5/8/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	

Note:

1. The PM 10 readings at Station 12 (110 Greenwich Street [roof level]) on May 7 and 8, 2008 were not available on account of instrument malfunction.