

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-2/13/2008	Southwest Area (sidewalk bridge level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST2-2/13/2008	Southeast Area (sidewalk bridge level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST4-2/13/2008	Northwest Area (street-level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST10-2/13/2008	North Side Sidewalk Bridge	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST100-2/13/2008	Station 10 Field Duplicate	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST11-2/13/2008	90 Trinity Place (roof level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST12-2/13/2008	110 Greenwich Street (roof level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST13-2/13/2008	Marriott Hotel, 38th Floor (roof level)	2/13/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST1-2/14/2008	Southwest Area (sidewalk bridge level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-2/14/2008	Southeast Area (sidewalk bridge level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST4-2/14/2008	Northwest Area (street-level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST5-2/14/2008	Firehouse #10 (roof level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST10-2/14/2008	North Side Sidewalk Bridge	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST100-2/14/2008	Station 10 Field Duplicate	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-2/14/2008	90 Trinity Place (roof level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST12-2/14/2008	110 Greenwich Street (roof level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST13-2/14/2008	Marriott Hotel, 38th Floor (roof level)	2/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	

- Note:
- PM 2.5 readings at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on February 13 and 14, 2008 were not available on account of power failure.
  - PM 2.5 reading at Station 5 (Firehouse #10 [roof level]) on February 13, 2008 was not available on account of power failure.