

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-5/26/2009	Southwest Area (sidewalk bridge level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-5/26/2009	Southeast Area (sidewalk bridge level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST4-5/26/2009	Northwest Area (street-level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST5-5/26/2009	Firehouse #10 (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST10-5/26/2009	North Side Sidewalk Bridge	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST100-5/26/2009	Station 10 Field Duplicate	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST11-5/26/2009	90 Trinity Place (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST12-5/26/2009	110 Greenwich Street (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST13-5/26/2009	Marriott Hotel, 38th Floor (roof level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST14-5/26/2009	West Face - South end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST15-5/26/2009	South Face - East end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST16-5/26/2009	East Face - North end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST17-5/26/2009	North Face - West end at corner (scaffolding level)	5/26/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	