

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>10</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>10</b>			
SILICA-ST1-2/7/11	041102825-0001	Southwest Area (sidewalk bridge level)	2/7/11	3.72	Silica	NIOSH 7500 XRD	EMSL	2/9/11	< 1	No	No	
SILICA-ST2-2/7/11	041102825-0002	Southeast Area (sidewalk bridge level)	2/7/11	3.67	Silica	NIOSH 7500 XRD	EMSL	2/9/11	< 1	No	No	
SILICA-ST5-2/7/11	041102825-0003	Firehouse #10 (roof level)	2/7/11	3.69	Silica	NIOSH 7500 XRD	EMSL	2/9/11	< 1	No	No	
SILICA-ST23-2/7/11	041102825-0004	Northwest Area (sidewalk bridge level)	2/7/11	3.73	Silica	NIOSH 7500 XRD	EMSL	2/9/11	< 1	No	No	
SILICA-ST1-2/8/11	041102912-0001	Southwest Area (sidewalk bridge level)	2/8/11	3.7	Silica	NIOSH 7500 XRD	EMSL	2/10/11	< 1	No	No	
SILICA-ST2-2/8/11	041102912-0002	Southeast Area (sidewalk bridge level)	2/8/11	3.51	Silica	NIOSH 7500 XRD	EMSL	2/10/11	< 1	No	No	
SILICA-ST5-2/8/11	041102912-0003	Firehouse #10 (roof level)	2/8/11	3.56	Silica	NIOSH 7500 XRD	EMSL	2/10/11	< 1	No	No	
SILICA-ST23-2/8/11	041102912-0004	Northwest Area (sidewalk bridge level)	2/8/11	3.66	Silica	NIOSH 7500 XRD	EMSL	2/10/11	< 1	No	No	

Note:

1. No sampling was conducted on 2/6/2011 due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.